

Temat: Skoroszyce, ul. Braterstwa Broni													
nr otworu:		S1		nr sondowania: SL1									
WYKRES SONDOWANIA SONDĄ LEKKĄ SL (DPL)													
	luźny	średnio zagęszczony	zagęszczony	bardzo zagęszczony	głębokość [m p.p.t.]	litologia	\overline{N}_{10}	I_D	I_s				
0,2-0,1					0,0-0,2	gleba	5						
0,4-0,3					0,2-0,7	nB[Po]	18						
0,5-0,6					0,7-1,1	Gp+KO	15						
0,7-0,8					1,1-3,8	Ps+KO//P _d	16	0,59	0,948				
0,9-1,0													
1,1-1,2													
1,3-1,4													
1,5-1,6													
1,7-1,8													
1,9-2,0													
2,1-2,2													
2,3-2,4													
2,5-2,6													
2,7-2,8													
2,9-3,0													
3,1-3,2													
3,3-3,4													
3,5-3,6													
3,7-3,8													
3,9-4,0													
4,1-4,2					3,8-4,1	Gpz+Ż	13						
4,3-4,4					4,1-6,0	Po	20	0,63	0,96				
4,5-4,6													
4,7-4,8													
4,9-5,0													
5,1-5,2													
5,3-5,4													
5,5-5,6													
5,7-5,8													
5,9-6,0													
6,1-6,2													
6,3-6,4													
6,5-6,6													
6,7-6,8													
6,9-7,0													
7,1-7,2													
7,3-7,4													
7,5-7,6													
7,7-7,8													
7,9-8,0													
8,1-8,2													
8,3-8,4													
8,5-8,6													
8,7-8,8													
8,9-9,0													
					Załącznik 7.1.								